**CASE HISTORY** 



# SAND STONE SURFACE

STATUE OF UNITY C/O L&T

Structure **CONCRETE** 

Category **GENERAL** 



### Structure:

Sand Stone Surface

#### **Client:**

Statue of Unity c/o L&T

## **Surface Preparation:**

Water Jetting

### **Product:**

TC Leak Proof

Solvent Water Leakages Issue

### **INTRODUCTION**

TOUGH COATINGS takes great pride in the privilege of contributing to a project of such global significance—the world's tallest statue.

Our expertise was crucial in addressing water leakage issues that surfaced on the gallery from the outer surface. Swift and efficient, our team wasted no time in formulating a comprehensive solution to safeguard this iconic structure.

The successful resolution not only underlines our commitment to excellence but also reinforces our capability to deliver timely and effective solutions even in the face of unique challenges. It's an honour for TOUGH COATINGS to play a role in preserving and enhancing the integrity of this monumental achievement.



